

Service Information

1. Model Name:

MX-M3050/M3550/M4050/M5050/M6050, MX-M3070/M3570/M4070/M5070/M6070, MX-M2630, MX-M2651/M3051/M3551/M4051/M5051/M6051, MX-M3071/M3571/M4071/M5071/M6071, MX-M6570/M7570

2. Subject:


CHANGE OF HDD

3. Description:

HDD usable for above models has been registered as service part to stabilize parts supply.

*There is no visible difference.

Location (Excerpt from **V21** PWB section 2 in Parts Guide for MX-M2651 series)



4. Action: Immediately after issuance of S/I

5. Parts Action:

Ref. No.	Model name	Destination	P/G No.	Current Parts	New Parts	Price rank	Q'ty	Parts name	Effective time	Inter-change-ability	Note	
				Parts code	Parts code							
1	MX-M3050 MX-M3550 MX-M4050 MX-M5050 MX-M6050 MX-M3070 MX-M3570 MX-M4070 MX-M5070 MX-M6070 MX-M2630	ALL	58 -20	DUNT-9232FCPZ	DUNT-9232FCP4	CC	1	HDD	-	1		
	58 -20		DUNT-9232FCPZ	DUNT-9232FCP5	CF	1	HDD	1				
	V21 -20		DUNT-9232FCPZ	DUNT-9232FCP4	CC	1	HDD	1				
	V21 -20		DUNT-9232FCPZ	DUNT-9232FCP5	CF	1	HDD	1				
	V21 -32		DUNT-9232FCPZ	DUNT-9232FCP4	CC	1	HDD	1				
	V21 -32		DUNT-9232FCPZ	DUNT-9232FCP5	CF	1	HDD	1				
	MX-M6570 MX-M7570											
<Interchange>												
1. interchangeable.						4. Not interchangeable.						
2. Current type can be used in place of new type. New type cannot be used in place pf current type.						5. Interchangeable if replaced with same types of related parts in use.						
3. Current type cannot be used in place of new type. New type can be used in place of current type						6. Others.						
Parts marled with “△” is important for maintaining the safety of the set. Be sure to replace these parts with specified ones for maintaining the safety and performance pf the set												